



# Rebate Handle Connector

First, you will need to advise us where the handle is located on your window: Top, Bottom, Left or Right.

Next, you will need to measure from the edge of the beading to the centre of your handle. This allows us to determine the exact location of the connector. How you measure, depends on the location of your handle.



If the handle is located on the right or the left side of your window, you will need to measure from the beading at the top of the window to the centre of your handles turning spindle.

If the handle is located on the top or bottom of your window, you will need to measure from the beading on the left side of the window to the centre of your handles turning spindle.

Please Note: The centre measurement may not always be located where the key hole is.